

J. Jeffrey Huber Daily Report 9/24/20

River inspection – 0630 (Corey A. Crew) a crew of 5 person started at the intake and walked downstream one mile and surveyed for any debris. Plastic was found 200 yards downstream. This plastic came from the spillway. The missing plastic was noticed in the morning upon inspection of the structure. All plastic was recovered.

Construction – Crews continued with work on the coffer dam. Crews set up dewatering in accordance with plan & permits.

JH – Talked with Crew throughout the day about construction methods and impact to environment. Talked crew about containment and inspection of equipment for leaks. Talked with everyone about following the work plan and the need for environmental controls. It was well received.

JH – Foreman discovered a small fuel leak on a pump. Pump was immediately shutdown and repaired. Pump was in containment. No fuel breached the containment or was observed

JH – 1400. Correy K. noticed a potential to release turbid water. JH asked that an excavator be used to build interceptor dike to contain. No turbid water reached the Puyallup River.

JH - 1500 JH takes walk half mile downstream from the intake to inspect for debris or foreign objects. None observed or recovered

JH – 1800 Crew begins to prep sheet piles for the following day.

JH – Fish Biologist in place to observe fish ladder.

Sincerely,

J. Jeffrey Huber Encore Environmental Representing Electron Hydro

